VZCZCXRO4993 PP RUEHIK RUEHYG DE RUEHBUL #1719/01 1071047 ZNR UUUUU ZZH P 171047Z APR 06 FM AMEMBASSY KABUL TO RUEHC/SECSTATE WASHDC PRIORITY 9641 INFO RUEHZG/NATO EU COLLECTIVE PRIORITY RUEHAD/AMEMBASSY ABU DHABI PRIORITY 1540 RUEHDBU/AMEMBASSY DUSHANBE PRIORITY 0196 RUEHIL/AMEMBASSY ISLAMABAD PRIORITY 3230 RUEHNE/AMEMBASSY NEW DELHI PRIORITY 6862 RUEHDE/AMCONSUL DUBAI PRIORITY 4371 RUEKJCS/OSD WASHDC PRIORITY RUEKJCS/JOINT STAFF WASHDC PRIORITY RHMFISS/CDR USCENTCOM MACDILL AFB FL PRIORITY RUEHUNV/USMISSION UNVIE VIENNA PRIORITY 1280 RUCNDT/USMISSION USUN NEW YORK PRIORITY 2439 RUEHGV/USMISSION GENEVA PRIORITY 5849 RHEHAAA/NSC WASHDC PRIORITY RUEAIIA/CIA WASHDC PRIORITY RHEFDIA/DIA WASHDC PRIORITY RUEATRS/DEPT OF TREASURY WASHDC PRIORITY RUCPDOC/DEPT OF COMMERCE WASHDC PRIORITY RULSDMK/DEPT OF TRANSPORTATION WASHDC PRIORITY 0062 RUEANHA/FAA WASHDC PRIORITY

UNCLAS SECTION 01 OF 02 KABUL 001719

SIPDIS

SENSITIVE SIPDIS

DEPARTMENT FOR SCA/FO, SCA/A, EB/OTP, EB/CBA NSC FOR AHARRIMAN, AMEND CENTCOM FOR CG CFC-A TREASURY FOR PARAMESWARAN COMMERCE FOR AADLER AND ITA BLOPP TRANSPORTATION FOR DMODESITT FAA FOR JHANCOCK AND TMARZIN

E.O. 12958: N/A TAGS: <u>EAIR ECON AF</u>

SUBJECT: ARIANA FLIGHTS TO UAE SUSPENDED

a resumption of service. End summary.

REF: A. 05 KABUL 4140

<u>¶</u>B. KABUL 0444

KABUL 00001719 001.2 OF 002

Sensitive but Unclassified. Not for Internet distribution.

Summary

- 11. (SBU) Afghan Ministry of Transport officials informed Embassy's FAA representative that an April 14, 2006 ramp inspection of an Ariana aircraft by UAE Civil Aviation Authorities found numerous, serious safety infractions and violations. UAE authorities allowed the plane to return to Kabul without passengers but suspended all/all Ariana operations in the UAE until further notice. With over fifty percent of Ariana, s passenger seat revenues generated from UAE traffic, this suspension will have drastic implications for Ariana, s already fragile financial status. The Afghan Ministry of Transport and Ariana Airlines sent a team, including Post's FAA representative, to Abu Dhabi to explore
- 12. (SBU) Afghan civil aviation authorities informed us that on April 14, 2006, UAE's General Civil Aviation Authority (GCAA) conducted a ramp inspection on Ariana's flight AFG401, a Boeing 727-200 aircraft. The inspectors found 17 major safety infractions. The flight manual onboard was not issued

to the operator. There was no operational flight plan with fuel planning, so compliance with fuel requirements could not be verified. No lifevests or passenger safety briefing cards were onboard for economy class passengers. The flight engineer's license did not include a medical certificate and the Captain's medical certificate was invalid. The air operating certificate displayed on board had expired on April 1, 2006. The insurance certificate expired almost a year ago. There was one emergency locator transmitter onboard, but its certification had expired in July 2004. The minimum equipment list onboard was not approved by the state of registry for the operator. The total aircraft hours/cycles could not be established. The documents presented indicated that the last maintenance was done in January 2004 and that further maintenance was due 3,000 hours from that date. No noise certificate or radio license was onboard. There was no evidence to indicate that the aircraft was equipped with a ground proximity warning system that has a predictive terrain hazard warning function. These are all violations of International Civil Aviation Organization (ICAO) Annex 6 and UAE aviation regulations. The inspection report noted that these findings "give indication of the lack of safety and regulatory oversight by the State of Registry/Operator," in this case Afghanistan's Ministry of Transport (MOT).

¶3. (SBU) UAE authorities immediately grounded Ariana's flight AFG401. In a letter dated April 15th, GCAA informed the GoA,s MOT that the flight would only be permitted to depart UAE on a ferry flight (empty, no passengers). Further, GCAA asked for a meeting with Ariana and Afghan civil aviation authorities to discuss safety and regulatory oversight issues. GCAA suspended all Ariana operations in the UAE until the satisfactory conclusion of such a meeting. Representatives from MOT and Ariana left for Abu Dhabi on April 15th. The Minister of Transport asked Post's FAA representative to attend in an advisory capacity. He

KABUL 00001719 002.2 OF 002

departed for Abu Dhabi on April 16th. The Afghan team will meet with GCAA to try to negotiate a resumption of service.

Comment

14. (SBU) As detailed in reftels, MOT does not currently have the capacity to effectively regulate and oversee the safe operation of airlines. Mission support on capacity building and civil aviation legislation will improve MOT oversight in the medium to long term, but Ariana itself has been an obstacle to improving regulatory oversight. As a state-owned carrier that enjoys significant political backing, Ariana routinely disregards MOT regulatory requirements and instructions. GCAA's suspension of Ariana's service will have major repercussions if service is not restored quickly. As UAE traffic comprises over fifty percent of Ariana,s passenger traffic, this suspension will result in substantial revenue losses for an already financially strapped Ariana. This action follows on the heels of Ariana, s inclusion on a list of carriers banned from operating in the European Union a few weeks ago. The status of Ariana, s Boeing lease, a detailed analysis of Ariana, s financial situation, and Ariana,s plan for eventual privatization will be reported via septels. End comment. Norland